



GUEST

Equipment: Articulated Dump Truck

Exercise: Certification Assessment

Pass

Score: 100 %

Total Time: 0:00:32

Goals: 1

5/19/2020 9:40:35 AM

Description

Practice for core competency assessment

Metrics

Angle Relative to the Wall: 0 °	Fences Knocked Over: 0
Average Cycle Time: 0:00:06	Fences Touched: 0
Average Distance from Path 1: 0 m	Fuel Consumed: 0
Average Distance from Path 2: 0 m	Human Contact: 0
Average Distance from Path 3: 0 m	Idle Time: 0:00:33
Brake Usage: 0:00:00	Maximum Distance from Path 1: 0 m
Retarder Usage: 0 %	Maximum Distance from Path 2: 0 m
Braking Distance: 0 m	Maximum Distance from Path 3: 0 m
Cabin Flip Over: 0	Quantity of Carry-Back: 0 kg
Collisions: 0	Retarder Usage: 0:00:00
Cones Knocked Over: 0	Slip Count: 0
Cones Touched: 0	Spill-Off Quantity: 0 kg
Current Score: 100 %	Time in 4-Wheel Drive: 0:00:00
Cycles per Hour: 11	Time in 6-Wheel Drive: 0:00:00
Distance from Path 1: 0 m	Total Excavated Mass: 0 kg
Distance from Path 2: 0 m	Total Mass Moved: 100
Distance from Path 3: 0 m	Up Hill Start Distance: 0 m
Down Hill Start Distance: 0 m	Volume Spilled Outside of the Bin: 0 m ³
Electric Pole or Cable Contact: 0	Wind Speed: 0

Environmental Conditions

Initial environment conditions:

Cloud Cover	Few clouds
Daytime	
Fog Visibility	1200
Hour	12:00
Month	August
Precipitation Intensity	0% of maximum
Precipitation Type	None
Wind	0 km/h 0 °